Work Order ID 850 <i>May-31-12 3:43:32 PM</i>	060	*8	5060*							Page 1
Item ID: D212-664-10 Revision ID: Item Name: Crosstube Turn	·	Accept	*N900	0040	1100)*	Setup	Start Stop	*N	S1*
Start Date: 31/05/2012 Required Date: 14/06/2012 Reference:	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*	Cust Item Customer:						*N	S2*
Approvals: Process Plan QC:	n: MCJ Date	:: 12/06/01 Tooling: :: SPC (Y/N):		Pate:			Run	Start Stop	*N *N	R1* R2*
Work Center ID	Operation Description sion Nbr	Set Up/ Run Hou	Tool ID	Tool #	Plan Code	Accept Qty	t Rejo Qty		Reject Number	Insp. Stamp
D212-664-141 Rev	D (DEO)									
100	MORI SEIKI CNC LATHE LARCE Memo 1-Fill tube with sand of the same of the sam	0.00 & install plugs DT8534 on both end or Folio FA113 es only, **do not sand whole tube** brush file repeatedly with file card.	k.	•		 		Ø		07/an/
110 *110* QC	QC1- Inspect dimensions to dimen Memo	r coarser than 320 grit. sion sheet 0.00 0.00			-	_ 1.		J	-	-

12/66/04.

Dart Aerosp	pace Ltd
-------------	----------

W/O:		WORK ORDER CHANGES										
DATE	STEP	PROC	EDURE CHAI			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						·						
								-	, .			
				· vog								
Part No	:	PAR #:	Fault Categ	NC	R: Yes	No DQA	\ :	Date:				
		Resolution: QA: N/C Closed:										
NCR:		W	ORK ORDE	R NON-CONFO	DRMANCI	(NCR)	***************************************	· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descrip	Section B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector		
<u>-</u>												
						-				:		
				·								

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Dart Aerospace L	_td
------------------	-----

W/O: 8	5060	WORK ORDER CHANGES					
DATE STEP		PROCEDURE CHANGE		y Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		Aladini to be close efter NAT aspatia					17/20/02

Resolution:	Disposition:	QA: N/C Closed:	Date:
Part No: \$D212-664-101TR PAR #:	Fault Category:	NCR: Yes No DQA:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
	T	Description of NC		Corrective Action Section B		Verification	Approval	Annessal
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		Section C	Chief Eng	Approval QC Inspector	
-								
er want								
			1					
		,						
				~			_	

0.00

Memo

120

Quality Control

12 (6)11 TX)
mt 06-05

Page 4

Dart Aerospac	ce Ltd	
---------------	--------	--

Dart Aei	rospa	ce Lta	ì							
W/O:			1	WORK ORD	ER CHANGES					
DATE	STEP		PROC	EDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
7										.3
							y.			
									,	
	· ·	•	1						,	
Part No	:		PAR #:	Fault Category:		CR: Yes	No DQ	A :	_ Date: _	
	•	Resolution:		Disposition:	Q	A: N/C C	losed:		Date: _	
			3044	ADIC ADDED MAN	001150511411	- ///			· · · · · · · · · · · · · · · · · · ·	

NCR:		W	ICR)				
		Description of NC		Corrective Action Section B	Verificatio	n Approval	
DATE	STEP	Section A	Initial Chief Eng		gn & Section C		Approval QC inspector
	. · ·		·	•			
· .							
	- '.						
				* .			2
; :							i :
-							

DART AEROSPACE LTD	Work Order:	85060
Description: Crosstube Assembly (205/212/412 High Fwd)	Part Number:	D212-664-141
Inspection Dwg: D212-664-141 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	•	•
X	First Article	Prototype
لسسا		

	nspection Sheet awing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
	0.200	+/-0.010	.200	1	<u> </u>	vern.	cwc.08
	R0.063	+/-0:010	.063			Rb	0.000
	2.740	+0.005/-0.0002		739	برن	very	CW1 - 098
	5.097	+/-0.030	5.097.		9	1	0
	2.304	+0.005/-0.000	2.309		۰		
	2.340	+0.005/-0.000	2-345	<i>'</i>	*		
EA	2.398	+0.005/-0.000	2-403			v	
SID	2.448	+0.005/-0.000	2,458		a		<u> </u>
1 7	2.498	40.005/-0.000) 503	٠-			. *
*	2.549	+0.005/-0.000	2554	s			
	2.599	+0.005/-0.000	2 603	/	, , , , , , , , , , , , , , , , , , ,		* *
	2.671	+0.005/-0.000	2-6.77			3	
	2.701	+0.005/-0.000	2.703	. //.	-	V	
,							•
	0.200	+/-0.010	.200	7		VIVI	CUR-06.
	*R0.063 🗯	O +/-0.010	.063		•	RG.	
	2.740	+0.005/-0.000	2.740			vern	surci 06
	5.097	+/-0.030	5.105			1	*
	2.304	+0.005/-0.000	2.308				4
8	2.340	+0.005/-0.000	2.345	*			y e
	2.398	+0.005/-0.000	2,463			ź.	
SIDE	2.448	+0.005/-0.000	2.453		·		•
	2.498	+0.005/-0.000	2.503	_,			
:	2.549	+0.005/-0.000	2.554				
	2 599	+0.005/-00000	2-603		•		
	2.671	+0.005/-0.000	2-677		\$	17	7. 9. 4
	2.701	+0.005/-0.000	7-701 1			. U	St. 12.
	126.514	+/-0.020	126.520			tape	16-22

Measured by: 97971 Audited by: Prototype Approval: N/A
Date: 12/06/03 Date: 12-6-6 Date: N/A

∍Rev	Date	Change		Revised by	Approved
_ A	05.04.27	New Issue (P/O D412-664-101)	* * 5 %	KJ/JLM	
В	06.03.15	Tolerance revised for 5.097 per Dwg Rev update		KJ/JLM	
C		Dwg Rev updated		KJ/JLM	
. D	10.02.02	Dimension 126.514 was 126.51	6	KJ KJ	- 11

	-									
W/O:]		V	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									,	
		,	-							
										
Part No	•	PAR #:	Fault Ca	tegory:	_ NCR: Yes	Date: _				
					QA: N/C Closed: Date:					
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE (NCR)			,	
DATE	CTED	Description of NC			ion B	Verific	ation	Approval	Approvai	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC inspector	
		·	·							
-										
									,	



Item	Qty -141	Qty -141B	Part Number	Description
1	X		D212-664-141	CROSSTUBE ASSEMBLY (205/212/412 HIGH FWD)
2		Х	D212-664-141B	CROSSTUBE ASSEMBLY (214 HIGH FWD)
3	. 1	1	D6005-128	CROSSTUBE
4	2	2	D2893-1	SUPPORT
5	4	4	D3595-063-450	RUBBER CUSHION
6	4	4	MS21920-25	CLAMP (OR MS21920-26)
7	A/R	A/R	MAGNOBOND 6398	ROCKWELL SPECIFICATION RBO-120-023 ADHESIVE (TEXTRON/BELL SPEC. 299-947-100, TYPE II, CLASS 2 ADHESIVE)

GENERAL NOTES:

1) MATERIAL: MANUFACTURED FROM D6005-128

FINISHED LENGTH = 126.514±0.020 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2 PAINT OUTSIDE PER DART QSI 005 4.2

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

4) UNITS: INCHES UNLESS OTHERWISE NOTED.

BREAK SHARP EDGES: 0.005 TO 0.010 MAX.

IDENTIFICATION: SCRIBE DART PART NUMBER "D212-664-XXX" AND BATCH NUMBER ON INSIDE OF CUFF USING VIBRATING STYLUS

WEIGHT: D212-664-141 = 33.6 lbs (PER IIN-D212-664)

D212-664-141B = 33.6 lbs (PER IIN-D212-664)

PART IS SYMMETRIC ABOUT CENTERLINE.

RUN CUTTER OFF PART. BLEND OUT EDGE LONGITUDINALY, TRANSITION SHOULD BE SMOOTH.

10) BEND PROGRESSIVELY WITH A MINIMUM OF 3 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D.

11) LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038.

12) INSTALL D2893-1 SUPPORT USING 0.03* TO 0.06* THICK LAYER OF MAGNOBOND 6398 TO THE SURFACE OF D2893-1 THAT WILL BE IN CONTACT WITH THE CROSSTUBE PER QSI 015. LET CURE FOR 12 HOURS AFTER INSTALLATION AND PRIOR TO PACKAGING.

13) INSTALL MS21920-25 CLAMPS (OR -26) WITH D3595-063-450 RUBBER CUSHIONS TO SECURE THE D2893-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE OPPOSITE OF CROSSTUBE SUPPORT

14) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.

15) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING.

SHOP COPY RETURN TO ENGINEERING **UNCONTROLLED COPY** SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER 0. 85060 MCJ 12/06/01


REHOVED FROM WIDER REVIEW PER UNDER REVIEW FON HIT- GIA

DEO ATTACHED


D	REORG TO CUF REMOV & B6-3)	SANIZED VIEW RRENT STAND 'ED REF & ADE : RELOCATED) TURNING DE	SENERAL NOTES/PART LIST; SADD REFORMATED DRAWING ARDS; ADD -141B (ZN B4-2, D4-2); D TOLERANCES (ZN B4-3, C6-3, C8-3 FLAG #6 PER PAR 08-046 (ZN A5-3); TAIL & UPDATED TOLERANCE TO	RF	09.09.30			
С			SION STRIP; ADD MAGNOBOND VERSE CLAMPS	PH	07.03.08			
₿.	ADD H SKIDT	OLES FOR CO	OMPATABILITY WITH BHT/AA	PH	05.02.04			
Α	NEW IS	SSUE		PH	00.12.12			
REV.			DESCRIPTION	BY	DATE			
DESIGN		PH	DART AEROSP	ACF	LTD			
DRAWN		RF	HAWKESBURY, ONTARI					
CHECKE	D	q)	DRAWING NO.		REV. D			
MFG. AF	PR.	187	D212-664-141	S	HEET 1 OF 4			
APPRO\	/ED	10	TITLE		SCALE			
DE APP	₹.		XTUBE ASS'Y (205/212/412	HI FW	D) NTS			
DATE	09.0	9.30	COPYRIGHT © 2000 BY DART AEROSPACE LTD THIS DOCUMENT IS ENVIATE AND COMPIDENTIA, AND IS SUPPLIED OF THE EXPRESS CONTROL THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMPED OR COMMUNICATION TO NOT ONE PERSON WITHOUT					

	P								
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	Part No:								
				·				<u></u>	
Part No	•	PAR #:	Fault Cat	degory:	NCR: Yes	No DQ	A:	Date:	
		esolution:	Dispositi	ion: <u>`</u>	QA: N/C C	osed:		Date: _	
NCR:		1	WORK ORI	DER NON-CONFORMA	NCE (NCF	?)			
DATE	CTED	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	k Secti	ion C	Chief Eng	QC Inspector
								:	

									,
	ļ								




W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No);	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date: _	
		solution:	Disposition	:	_ QA: N/C C	losed:		Date:	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)	•		
DATE	STEP	Description of NC		Corrective Action Secti	on B Sign		cation		Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Date		ion C	Chief Eng	QC Inspector
				1,,,,					
-									
•									r
					}			,	



Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	CEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							,			
F										
	·									
		PAR #:	Fault Cate	gory:	NCR: `	Yes N	o DQ	A :	Date:	
Re		esolution:	Disposition	on: <u>'</u>	QA: N/	C Clos	sed:		Date: _	
NCR:		\	WORK ORD	ER NON-CONFORM	ANCE (I	NCR)	•••			
DATE	STEP	Description of NC	Initial	Corrective Action Section B Initial Action Description			Verific			Approval
		Section A	Chief Eng	Chief Eng		ign & Date	Section	on C	Chief Eng	QC Inspector
·										
								•		
										:
								N		ž.
										,



Q

-

W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·					
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	າ: `	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCI	R)			
		Description of NC		Corrective Action Section B			cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
								urante de la companie	
								1	

DRAWING NO.	TITLE			DART AE	ROSPACE LTD	D.E.O. NO.		SHEE	T NO.	SCALE
D212-664-141	XTUBE ASSY (2	05/212/412 HI F	WD)	ENGINE	ERING ORDER	D212-66	4-141 <u>-</u> D-1	SHEET	1 OF 2	NTS
DRAWN	CHE	CKED //	/ N	MFG. APPR.	B	APPROVED	MP.	DE APPR.	-#	
DATE 11.0	4.07 DATE	E)),	D),)] [DATE	11.04.12	DATE	11/04/12	DATE	11.04.12	

PURPOSE:

ADD AN INSPECTION WINDOW TO UNDERSIDE OF CROSSTUBE.

25060



CHANGE:

NOTES 2 OF SHEET 1 IS AMENDED AS FOLLOWS:

IS:

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2

MASK UNDERSIDE OF CROSSTUBE AS SHOWN (HATCHED AREA) AND

PAINT OUTSIDE PER DART QSI 005 4.2 REMOVE MASKING AND APPLY CLEAR COAT

WAS:

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2

PAINT OUTSIDE PER DART QSI 005 4.2


UNDER REVIEW

EC 11-614

11.07.28

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WHITTEN DEPRISON WOUND HAVE REPORTED FE IT

Duit Aci	Jopade	LW							
W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						2.			
Part No	:	PAR #:	Fault Cat	egory:	NCR: Ye	s No DC	A:	Date: _	
		esolution:	Dispositi	on: <u>`</u>	_ QA: N/C	Closed: _		Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC Section A	Corrective Action Initial Action Descrip		on B Sign		cation tion C	Approval Chief Eng	Approval QC Inspector
	1.	Section A	Chief Eng	Chief Eng	Da	te		Officer Ling	QO Mapeciol
		·							
							•		
	I		1	•	1	1		l	1



Dart Aerospace Ltd	Da	rt A	ero	spa	ce l	Ltd
--------------------	----	------	-----	-----	------	-----

Duit Aq	oopaoc	Liu								
W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PRO	CEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,								,
Part No):	PAR #:	Fault Cate	gory:	_ NCR: `	Yes N	o DQ	A:	Date:	
	R	esolution:	Dispositio	n: <u>`</u>	QA: N/	C Clos	sed:		Date: _	
NCR:		· V	VORK ORD	ER NON-CONFORM	ANCE (I	NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sect Action Description Chief Eng		ign & Date	Verific Secti	cation on C	Approval Chief Eng	Approval QC Inspector
				<u> </u>						
	·									
		·								
		,								:
]					

DRAWING NO.	TITLE REV. D	DART AEROSPACE LTI	D.E.O. NO.	SHEET NO.	SCALE
D212-664-141	CROSSTUBE ASS'Y (205 HI FWD)	ENGINEERING ORDER	D212-664-141-D-2	SHEET 1 OF 1	NTS
DRAWN //	CHECKED A>S	MFG. APPR.	APPROVED MA	DE APPR.	
DATE 11.07	.15 DATE 11.07.20	DATE 11.07.21	DATE 11/07/21	DATE 11.07.2	

PURPOSE:

REPLACE MAGNOBOND WITH PROSEAL.

2500

CHANGE:

IS:

ltem	Qty -141	Qty -141B	Part Number	Description
7	A/R	A/R	PROSEAL 890 B-2	SEALANT, AMS-S-8802 CLASS B-2

WAS:

			,	T
7	A/R	A/R	MAGNOBOND 6398	ROCKWELL SPECIFICATION RBO-120-023
1	İ			ADHESIVE (TEXTRON/BELL SPEC. 299-947-100,
	<u> </u>			TYPE II, CLASS 2 ADHESIVE)

NOTE 12 & 15, SHEET 1 IS AMENDED AS FOLLOWS:

IS

- 12) TO INSTALL D2893-1.SUPPORT: ABRADE MATING SURFACE OF SUPPORT AND CROSSTUBE WITH 180-GRIT SANDPAPER AND REMOVE RESIDUE WITH MEK (OR EQUIVALENT). APPLY A 0.04" TO 0.07" THICK LAYER OF PROSEAL 890 CLASS B-2 (OR AMS-S-8802 CLASS B-2) SEALANT TO MATING SURFACE OF SUPPORT.
- 15) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING. PRIOR TO PACKAGING, RE-CHECK TORQUE ON CLAMPS AFTER PROSEAL 890 SEALANT HAS CURED FOR 72 HOURS.

WAS:

- 12) INSTALL D2893-1 SUPPORT USING 0.03" TO 0.06" THICK LAYER OF MAGNOBOND 6398 TO THE SURFACE OF D2893-1 THAT WILL BE IN CONTACT WITH THE CROSSTUBE PER QSI 015. LET CURE FOR 12 HOURS AFTER INSTALLATION AND PRIOR TO PACKAGING.
- 15) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING.



COPYRIGHT © 2011 BY DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT I NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT

Dail Aciospace Lia	Dart	Aeros	pace	Ltd
--------------------	------	--------------	------	-----

Duitho	. oopaoc	Liu		:					
W/O:			٧	VORK ORDER CHANGE	S				
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							•		
		· ·							
::				·					
				···-			<u> </u>		
Part No		PAR #:							
	Re	esolution:	_ Disposit	tion:	QA: N/C C	losed:		Date: _	
NCR:	,	W	ORK OR	DER NON-CONFORMA	NCE (NC	₹)			
		Description of NC		Corrective Action Section	ı B	Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	& Secti		Chief Eng	QC Inspector
·				·		and in the same of			:
		,	,						
				**************************************	•				
									t .
1	1	i e e e e e e e e e e e e e e e e e e e	1		1	f		I .	ı

DART AEROSPACE LTD	Work Order:	35060
Description: Crosstube	Part Number:	D212-664-1017
Inspection Dwg: () Rev: AA		Page of

WALL THICKNESS MEASUREMENT



	WALL	. THICKNESS I	WEASUREME	NT (IN)	Deviation	
Location	·w1	w2	w3	w4	Δw (max-min)	TOLERANCE
READING 1 L= 0"						The state of the s
READING 2 L= 21	244	.250	,251	.243	,	Transfer out to the state of th
READING 3	.356	,360	.359	.355		
READING 4 L= ,						0.030"
READING 5 L= 42	351	. 362	, 365	.353		Per source of the contract of
READING 6	. 257	. 247	. 240	. 247.	·	9
READING 7 L=						The state of the s

Calibration Result

Actual Block Thickness: 100 = 500

Sitescan 250 Measured Thickness: 100 - 500

